




# Outline of the Damage in Chiba Area due to The 2011 off the Pacific coast of Tohoku Earthquake

June 28, 2011  
Shoichi Nakai, Chiba University







## Affected Areas in Chiba Pref.




## Affected Areas in Chiba Pref.



## Affected Areas in Chiba Pref.









### Outline of the Damage in Urayasu City

Damage	Volume
No. of Victims	96,473
No. of Suffered Household	37,023
Liquified Area	1,455 ha
Damaged Sewage Systems	820 ha
Damaged Roads	112 km
Emergency Safety Check	8,878





## Land Use of Affected Area



## Damage Details



• After City of Urayasu


• 10



Miakegawa Junior High



Takasu District



Akemi Elementary Sch.



Private School

● After City of Urayasu

● 11



Maihama District



Central Park



Chidori District



Takasu District

● After City of Urayasu

● 12





● After City of Urayasu


● 13



● After City of Urayasu

● 14





### Damage of Sewage System

清掃車による土砂吸入作業

土砂流入による格管の閉塞状況

ポンプ設置による応急処置状況

応急対応パイプ工管設置

マンホール浮上状況

マンホール撤去後の安全対策状況

マンホールのずれ

管体のずれによる道路陥没応急復旧状況

道路陥没応急復旧後

**凡例**

- 管渠区域使用制限区域
- 管渠区域静置地帯
- 幹線管渠箇所
- ポンプ設置箇所
- 陥没箇所
- パイプ工施工箇所


元	例
管渠区域使用制限区域	管渠区域使用制限区域
管渠区域静置地帯	管渠区域静置地帯
幹線管渠箇所	幹線管渠箇所
ポンプ設置箇所	ポンプ設置箇所
陥没箇所	陥没箇所
パイプ工施工箇所	パイプ工施工箇所

<被害状況>

<応急対策>

● After City of Urayasu

● 16




### Number of Damaged Houses

	Damage Criteria	
	Previous Std	New Standard
Total Collapse	8	14
Near Collapse	0	1,419
Half Collapse	33	1,939
Partial Collapse	7,930	5,153
No Damage	1,028	1,270
<b>合 計</b>	<b>8,999</b>	<b>9,795</b>

• After City of Urayasu

## Change of Elevation before and after the Quake

### (1) Comparison between Two Times




**注意！**

- 現時点で国土地理院が基準点成果を一時利用停止していることから、本図面の作成に当たっては、震災前の基準点位置座標を用いて作成している。
- 今後、国土地理院から新座標が公開され次第、再計算を行い改めて作成を行うこととする。
- 従って、本図面については、暫定のものであるので注意をすること。
- データの精度は±15cm
- 海・河川は計測外となっているので特に色の意味はない。

After City of Urayasu

### (2) Difference between Two Times



**注意！**

- 現時点で国土地理院が基準点成果を一時利用停止していることから、本図面の作成に当たっては、震災前の基準点位置座標を用いて作成している。
- 今後、国土地理院から新座標が公開され次第、再計算を行い改めて作成を行うこととする。
- 従って、本図面については、暫定のものであるので注意をすること。
- データの精度は±15cm
- 海・河川は計測外となっているので特に色の意味はない。


**変化量(m)**

- > 0.9
- 0.7 ~ 0.9
- 0.5 ~ 0.7
- 0.3 ~ 0.5
- 0.1 ~ 0.3
- 0.1 ~ 0.1
- 0.3 ~ -0.1
- 0.5 ~ -0.3
- 0.7 ~ -0.5
- 0.9 ~ -0.7
- < -0.9


After City of Urayasu





## Affected Areas in Chiba Pref.




## Mihama-ku of Chiba City





## Recorded Ground Motions (Liq.)




## Summary of Ground Motions

Sites		PGA (cm/s/s)			PGV (cm/s)		
		NS	EW	UD	NS	EW	UD
C08	K-NET Urayasu	125.1	157.5	75.2	28.4	27.5	11.6
C09	K-NET Chiba	178.7	139.7	77.1	35.0	22.1	10.7
C24	K-NET Inage	234.4	202.5	85.6	30.7	31.5	14.0
kor	Upland (Inage)	185.0	202.5	139.2	24.9	22.1	13.9
Low	Lowland (Inage)	203.5	246.3	175.6	40.0	49.2	21.0
MAK	Makuhari Messe	244.0	274.1	128.0	29.4	36.1	12.2
mam	Inage-dai	188.2	206.4	147.0	24.3	21.5	12.6
nis	Slope shoulder	480.5	343.6	203.3	29.8	23.5	14.6
No3	Chiba Univ. No.3	157.6	172.1	90.7	22.8	22.6	11.1
No4	Chiba Univ. No.4	149.2	148.5	108.2	26.1	23.0	11.0
TDA	TEPCO Anesaki	83.5	74.5	53.6	19.4	21.2	9.7





## Liquefaction (Sand Boiling)




### Near Kaihin-Makuhari station

Heavy sand boiling and ground deformation along the sidewalk were observed.





# Liquefaction (Sand Boiling)




## Isobe district

Inside the residential area, a wide-spread sand boiling was observed.








## Shinminato district

In an industrial area, a large amount of sands were blown off from the gap of the road surface.



## Shin-Minato



The utility pole settled about 1 m.





Shin-Minato



Settlement of nearby ground


Shin-Minato



Settlement of nearby ground



# Liquefaction (Sand Boiling)




## Makuhari Messe (Convention center)

Strong motions were recorded near the event hall.



Parking Lot



Accelerometer

## QVC Marine Field (Baseball field)

The facility underwent restoration work until April 12, the opening day of the professional baseball game.



## K-NET Inage (Strong motion station)


Heavy sand boiling and several tilted utility poles were found around the strong motion station.



# Inage Kaihin Park




## Damaged Road (Emergency Rehabilitation)






## Damaged Road (Emergency Rehabilitation)




...  
Preliminary Study



## Grain Size Distribution of Boiling Sand




## Non-Liquified Areas




# Soil Profile and Liquified Area








## Depth of Alluvium and Lq. Area



## Liquefaction in Prev. EQ



## Summary

- In Chiba area located east of Tokyo, it was observed that
  - Liquefaction occurred extensively, especially in the reclaimed ground along the sea and along the river.
  - A large number of houses were damaged (tilted) due to liquefaction.
  - Lifelines were shutdown and roads were closed due to liquefaction.